



PROPERTY RESTORATION

Case Study: NEW LONDON PUBLIC SCHOOLS
Nathan Hale Arts Magnet School
New London, CT

Loss Event: Water Damage

Damage: Extensive water damage in classrooms and hallways.

THE PROBLEM

Nathan Hale Arts Magnet School sustained water damage throughout the facility after a component to the HVAC system malfunctioned, allowing cold air to enter from the exterior and freeze a pipe that burst after school hours.

The water caused damage to 13 classrooms, two storage/janitorial rooms, two restrooms, two large hallways, one stairwell and two exit corridors on the first and second floors of the building.

THE SOLUTION

The BELFOR response to the loss included:

- Immediate protection of contents and assets;
- Setting up containment to limit spread of dust and to establish drying chambers;
- Packing of all content within the classrooms, inclusive of storage cabinet, student benches and lockers, and sink locations due to affected walls;
- Thorough inspection and detachment of cabinetry and classroom fixtures as needed;
- Removal of materials as agreed upon by site walk through with representatives from the City of New London and the adjuster. Materials removed included: drywall, insulation, suspended ceiling tiles, vinyl cove base molding, and some cabinetry;
- Setting up of drying equipment and daily monitoring;
- Cleaning and sanitizing of exposed building materials as well as those left in place and dried through to completion;
- Cleaning of furniture and content.

BELFOR brought in a team of 87 project managers, sub contractors, technicians and general laborers. All mitigation and repair work was completed in 10 days.

SAVE THE DAY

- Two restrooms were affected on tiled walls common to hallways. BELFOR successfully dried these walls and cavities using a cavity drying system, saving the removal/replacement of insulation and tile work.
- BELFOR had vendors/suppliers on site day one to scope materials needed for repairs, ultimately shortening timelines for delivery to site.



"Having a trusted disaster recovery partner in place before a loss is vitally important. BELFOR's rapid response and expertise in handling our emergency at Nathan Hale Art's school proved integral to minimizing the impact and downtime to our staff and students. Thank you to the entire team at BELFOR."

PAUL GILLS
Risk Manager, City of New London

24/7 Emergency Number

800-856-3333

Corporate Headquarters:
185 Oakland Ave., Suite 150
Birmingham, MI 48009-3433
Toll Free: 888.421.4111
Direct : 248.594.1144
www.belfor.com

Commercial Services ▶

Fire Restoration | Water Extraction | Structural Cleaning & Decontamination | Dehumidification
Mold Remediation | Corrosion Control | Smoke and Soot Removal | Structural Shrink Wrap
Contents Restoration | Document and Media Recovery | Electronics Restoration
Equipment and Machinery Repair & Rebuild | Environmental Services
Semiconductor Services | Total Reconstruction Services | Consulting Services

Residential Services ▶

Smoke and Soot Removal | Water Extraction | Structural Dehumidification
Structural Cleaning & Decontamination | Mold Remediation | Environmental Services
Contents Restoration | Document and Media Recovery | Electronics Restoration
Reconstruction Services