

Case Study: WALTON'S FUNERALS & CREMATIONS Sparks, NV

Loss Event: Fire

Damage: Extensive Fire and Smoke Damage

THE PROBLEM

A fire that started on the outside of the Walton's Funerals & Cremations Center quickly moved into the eves of the building and the roof partially collapsed before fire departments from Sparks and Reno could extinguish the flames. The business has been part of the community for 44 years, but the building was deemed a "total loss" by the Sparks Fire Department.

Even though the fire did not reach any human remains, water damage from the firefighting efforts did create another problem. The cardboard boxes used to store cremains were rapidy degrading. It was a critical race against time to protect the cremains and re-catalog them before the identifying information on the degrading boxes was lost.

THE SOLUTION

BELFOR Property Restoration and BELFOR Environmental were trusted with the restoration project. Of highest priority, BELFOR Environmental removed, re-boxed and cataloged all cremains from damaged areas before any were lost to water and fire damage.

The scope of the project included:

- · scanning contaminated documents from damaged areas into a digital format;
- · demolition of the structure to the bare framing;
- · encapsulating the framing to smoke-seal and protect against odor; and,
- · performing asbestos abatement.

To complete the asbestos abatement, a containment system had to be constructed over and around the entire building. BELFOR brought in a 40-man crew of construction and engineering specialists to handle the containment, along with three large cranes (50, 75 and 90-ton). A three-piece truss superstructure – 20 feet high by 125 feet long by 95 feet wide – allowed BELFOR to shrink wrap the entire building and protect the area while BELFOR Environmental specialists safely performed the asbestos abatement.

"BELFOR were true professionals. They took control of the job and kept us informed of their progress. Their word was their bond."

TAMMY DERMODY
Owner
Walton's Funerals and Cremation









24/7 Emergency Number 800-856-3333

Corporate Headquarters: 185 Oakland Ave., Suite 150 Birmingham, MI 48009-3433 Toll Free: 888.421.4111

Direct : 248.594.1144 www.belfor.com

Commercial Services

Fire Restoration | Water Extraction | Structural Cleaning & Decontamination | Dehumidification Mold Remediation | Corrosion Control | Smoke and Soot Removal | Structural Shrink Wrap Contents Restoration | Document and Media Recovery | Electronics Restoration Equipment and Machinery Repair & Rebuild | Environmental Services | Semiconductor Services | Total Reconstruction Services | Consulting Services

Residential Services

Smoke and Soot Removal | Water Extraction | Structural Dehumidification Structural Cleaning & Decontamination | Mold Remediation | Environmental Services Contents Restoration | Document and Media Recovery | Electronics Restoration Reconstruction Services